

New Mexico TTCP Training and Certification Schedule

(Updated December 6th, 2023)

Lab 1 (L1) = Robert's Lab

Lab 2 (L2) = Joel's Lab

Classroom 1 (C1) = Old North ACNM Classroom

Classroom 2 (C2) = New North Classroom (east)

Classroom 3 (C3) = New North Classroom (west)

Classroom 2 & 3 (C2/3) = New Combined Classrooms

Note: All FIVE lab/classroom locations are at the ACNM/TTCP facility at 6135 Edith, NE, Alb.

December 2023

12-13	8:00 am on 12/12	Nuclear Densometer Certification	FULL	C1
14-15	8:00 am on 12/14	Soils Certification	6	L2
15	10:00 am on 12/15	<i>Traffic Control Re-Cert/Re-Test (Contact ACNM to register)</i>		C2
15	8:00 am on 12/15	<i>Storm Water Qualified Person (Contact ACNM to register)</i>		C1
18-20	8:00 am on 12/18	Aggregate Certification	11	L2
19-21	8:00 am on 12/19	HMA Certification	3	L1
21-22	8:00 am on 12/21	Concrete Certification	8	L2
15-16	CANCELLED 8:00 am	Concrete Certification	15	L2

January 2024

8-12	8:00 am on 1/8	Aggregate Training	10	L2
9	8:00 am on 1/9	<i>Traffic Control Technician (Contact ACNM to register)</i>		C2
9-11	8:00 am on 1/9	HMA Training	6	L1
10-11	8:00 am on 1/10	<i>Traffic Control Supervisor (Contact ACNM to register)</i>		C2
12	8:00 am on 1/12	Inertial Profiler Inspector Training	8	C1
17-18	8:00 am on 1/17	Nuclear Densometer Training and Radiological Safety Certification	FULL	L1
17-18	8:00 am on 1/17	Soils Training	8	L2
19	10:00 am on 1/19	<i>Traffic Control Re-Cert/Re-Test (Contact ACNM to register)</i>		C1
22-23	8:00 am on 1/22	Concrete Training	6	L2
23-25	8:00 am on 1/23	HMA Certification	5	L1
24-26	8:00 am on 1/24	Aggregate Certification	6	L2
26	8:00 am on 1/26	<i>Storm Water Qualified Person (Contact ACNM to register)</i>		C1
26	9:00 am on 1/26	<i>Radiation Safety Officer Training (Contact ACNM to register)</i>		C1
29-30	8:00 am on 1/29	Soils Certification	1	L2
30-31	8:00 am on 1/30	Nuclear Densometer Certification	3	C1
31-2/1	8:00 am on 1/31	Concrete Certification	9	L2

February 2024

2	8:00 am on 2/2	Seeding Inspector Certification	4	C1
5-9	8:00 am on 2/5	Aggregate Training	6	L2
6	8:00 am on 2/6	<i>Traffic Control Technician (Contact ACNM to register)</i>		C2
6-8	8:00 am on 2/6	HMA Training	6	L1
7-8	8:00 am on 2/7	<i>Traffic Control Supervisor (Contact ACNM to register)</i>		C2
12-13	8:00 am on 2/12	Concrete Training	12	L2
13-14	8:00 am on 2/13	Nuclear Densometer Training and Radiological Safety Certification	4	C1
14-15	8:00 am on 2/14	Soils Training	15	L2
16	10:00 am on 2/16	<i>Traffic Control Re-Cert/Re-Test (Contact ACNM to register)</i>		C1
19-21	8:00 am on 2/19	HMA Certification	4	L1
20-22	8:00 am on 2/20	Aggregate Certification	3	L2
23	8:00 am on 2/23	<i>Storm Water Qualified Person (Contact ACNM to register)</i>		C1

February 2024 (cont.)

26-27	8:00 am on 2/26	Soils Certification	15	L2
27-28	8:00 am on 2/27	Nuclear Densometer Certification	7	C1
28-29	8:00 am on 2/28	Concrete Certification	8	L2

March 2024

1	8:00 am on 3/1	Drilled Shaft Certification	6	C1
4-8	8:00 am on 3/4	Aggregate Training	15	L2
5	8:00 am on 3/5	<i>Traffic Control Technician (Contact ACNM to register)</i>		C2
5-7	8:00 am on 3/5	HMA Training	1	L1
6-7	8:00 am on 3/6	<i>Traffic Control Supervisor (Contact ACNM to register)</i>		C2
11-12	8:00 am on 3/11	Concrete Training	10	L2
12-13	8:00 am on 3/12	Nuclear Densometer <u>Training</u> and Radiological Safety Certification	12	C1
13-14	8:00 am on 3/13	Soils Training	11	L2
15	10:00 am on 3/15	<i>Traffic Control Re-Cert/Re-Test (Contact ACNM to register)</i>		C1
18-20	8:00 am on 3/18	HMA Certification	1	L1
19-21	8:00 am on 3/19	Aggregate Certification	15	L2
22	8:00 am on 3/22	<i>Storm Water Qualified Person (Contact ACNM to register)</i>		C1
25-26	8:00 am on 3/25	Soils Certification	10	L2
26-27	8:00 am on 3/26	Nuclear Densometer Certification	12	C1
27-28	8:00 am on 3/27	Concrete Certification	12	L2

TTCP and ACNM Class Registration - Ashley Primera aprimera@aconm.org (505) 344-2072, ext. 10

Please note that all classes in “red italics” are ACNM sponsored classes and may not be intended or necessary for all NMDOT personnel. Contact Ashley Primera to schedule ACNM classes.

- Please be aware that the fourth column of this schedule shows “Spots Available” and that represents the number of seats that are available for that class on the date of this schedule. Seats may continue to fill up and some classes may be FULL before the next updated TTCP Schedule is sent out.
- All NMDOT personnel shall schedule through their District TTCP Training Liaison.
- Remember your OJT documentation when you come to TTCP for Certification.
- Please cancel at least one working day (24 hours) prior to the start of class, if the one working day cancellation policy is not met a \$100.00 no show fee can be applied.
- **NOTE: For participation in the Nuclear Densometer Training/Certification, you must bring your personal monitoring badge provided by your employer or District representative. The Environmental Department is no longer going to allow TTCP to use loaner badges for Nuclear Densometer Training and Radiological Safety Certification or Nuclear Densometer Certification. If the scheduled technician attending either of these classes does not have their assigned monitoring badge by the time the hands-on demonstration is done then they cannot complete Nuclear Densometer Training/Certification NO EXCEPTIONS.**