

The 2018 edition of the Virginia Construction Code will apply to all permit applications submitted on or after July 1, 2022. This is a summary of important changes adopted in the 2018 edition of the code. This is not a comprehensive list of every change.

Structural

Code	Requirement	What Changed
Section		
County	Chesterfield County has updated the	Soil testing methods updated to current code
Policy	Residential Soil Testing and Footing Design	requirements. The footing design for non-expansive
(Based on	Requirements policy.	soils shall comply with the current code. See attached
R301.1.3,		soil policy.
R401.4 &		
R403.1.8)		
Table	Projections can now be less than 5' from the	
R302.1(1)	property line if it is 1 hour rated on the underside, or heavy timber, or fire-retardant treated wood	Previously projections within 2 feet of the property line were not allowed and from 2 feet to 5 feet had to be 1
		hour fire rated. Additional options of how to achieve the rating were added.



Code Section	Requirement	What Changed
R310.3	When an emergency escape and rescue opening is below the adjacent grade, an area well shall be provided. Area wells shall be at least 36" wide.	New section added.
R311.7.3	A flight of stairs shall not have a vertical rise greater than 151 inches between floor levels or landings.	Previously, maximum rise was 147 inches between floor levels or landings
R311.7.11	Alternating tread devices are allowed to be used as an element of a means of egress for lofts, mezzanines and similar areas of 200 gross square feet or less where such devices do not provide exclusive access to a kitchen or bathroom.	New exception added



Code Section	Requirement	What Changed
R315.5	Where more than one carbon monoxide alarm is required to installed within a dwelling unit, the alarm devices shall be interconnected.	New section added.
R317.3	Staples for preservative treated wood are required to be stainless steel	Previously galvanized staples were allowed.
R324.6.2.2	Rooftop mounted solar panels are not permitted to be installed directly below an emergency escape and rescue opening. A pathway not less than 36 inches wide shall be provided.	New section added
R403.1.6	The centerline of the anchor bolt shall be located a minimum of 1.75 inches from the edge of the sill plate.	The 2015 code required the anchor bolts to be in the middle 1/3 of the sill plate



Code Section	Requirement	What Changed
	Dehumidification sized to provide 70 pints of	An additional option was added for unvented crawl
R408.3	moisture removal per day from every 1000	spaces. A dehumidifier can now be used as an
	square feet of unvented crawl space floor area.	alternative to conditioned air and transfer grille.
	Garage doors are required to have permanent	New section added
R609.4.1	labels from the manufacturer with the design criteria	
R703.2	Detached accessory structures now required to	Detached accessory structures were not required to
	have a water resistive barrier.	have a water resistive barrier.
N1101.14	An energy certificate shall be posted near the	New section added
	furnace, electrical panel or utility room. The	
	certificate shall identify energy efficiency	
	information for the building and systems.	
N1102.1.2	The fenestration u-factor has been lowered to	Previous code allowed a 0.35 u factor.
	0.32.	
N1102.1.2	R-38 ceiling insulation must cover 100% of the	R-38 insulation cannot be compressed.
	ceiling area and extend over top plates without	
	being compressed. If R-38 cannot fit without	
	being compressed, then R-49 is required.	
	Ceilings without attic spaces are required to	This clarifies that the insulation must extend to the
	have a minimum R-30 insulation and the	outside of the wall plate.
	insulation shall extend over the top of the wall	
N1102.2.2	plate to the outer edge. The reduction is	
	limited to 500 square feet.	



Mechanical

Code	Requirement	What Changed
Section		
M1502.4.2	Where dryer exhaust ducts are enclosed in wall or ceiling cavities the duct shall not be deformed to fit in the cavity.	2×4 with furring strip $5^{1/2}$ in.
		Can no longer run dryer exhaust duct in a 2x4 wall cavity.
M1502.3.1	The passageway of dryer exhaust duct terminals shall be undiminished in size and shall provide an open area of not less than 12.5 square inches	Clarifies that the duct cannot be deformed. 12.5 square inches is equivalent to the area in a 4-inch round duct.
N1103.3.3	HVAC Ducts shall be pressure tested to determine air leakage and a written report of the results shall be provided to the code official	Chesterfield County will now require the report to be onsite for the final mechanical inspection.



Plumbing & Fuel Gas

Code Section	Requirement	What Changed
P3012	Relining of building sewers and building drains is now acceptable.	BEFORE AFTER
P3114.8	Air admittance valves shall not be installed on outdoor vent terminals for the sole purpose of reducing clearances to air intakes	Clarification that vents shall be a minimum 10 feet from intakes.
G2447.2	Commercial cooking appliances are now permitted in dwelling units when installed per an engineered design and the manufacturer's installation instructions.	An exception was added.



Electrical

Code Section	Requirement	What Changed
E3902.4	All lighting outlets not exceeding 120 volts that are located inside a crawl space shall be GFCI protected.	Added the lights to the existing requirement for receptacles.
E3703.5	All attached garages or detached garages with electrical power are required to have at least one 120-volt, 20 ampere branch circuit. This circuit is limited to receptacle outlets in the garage and readily accessible outdoor receptacles.	New section added
E3902.16	AFCI protection required for kitchens, family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreation rooms, closets, hallways, laundry areas and similar rooms or areas. AFCI protection is not required where GFCI protection is required.	Expanded the requirement to include additional rooms and areas. Previous code only required AFCI protection in the bedrooms.



Section	
	ows TC-ER cable to be used for installation of whole use generators.



Chesterfield County, Virginia Department of Building Inspection

9800 Government Center Parkway – P.O. Box 40 – Chesterfield, VA 23832 Phone: (804) 748-1057 – Fax: (804) 751-2249 – Internet: chesterfield.gov

Ronald W. Clements Jr. Building Official

Residential Soil Testing and Footing Design Requirements

Updated 7.1.22

SOIL TEST REQUIREMENT

A soil test to determine the potential for expansive soils shall be performed by a Virginia registered design professional (RDP) and a report of the soil test shall be submitted with the building permit application for all new residential dwellings or additions.

Soils meeting provisions 1, 2, and 3 below (all three), or provision 4 below shall be considered expansive:

- 1) Plasticity Index (PI) of 15 or greater, determined in accordance with ASTM D4318 and,
- 2) More than 10 percent of the soil particles pass a No. 200 sieve, determined in accordance with ASTM D422 and,
- 3) More than 10 percent of the soil particles are less than 5 micrometers in size, determined in accordance with ASTM D422

OR

4) Expansion Index greater than 20, determined in accordance with ASTM D4829

The soil testing methods shall utilize ASTM D4318 and D422, or ASTM D4829 to determine if the soil is expansive per the provision listed above. The scope of the soil test including the number and types of borings or soundings, the equipment used to drill or sample, the in-situ testing equipment and the laboratory testing program shall be determined by the RDP.

The test report shall include:

- 1. The report shall clearly state if expansive or non-expansive soils were encountered based on the provisions listed above.
- 2. A plot showing the location of the soil investigations.
- 3. A record of the soil boring and penetration test logs and soil samples.
- 4. A record of the soil profile

- 5. Elevation of the water table, if encountered
- 6. Special design and construction provisions for foundations of structures founded on expansive soils, as necessary
- Exceptions: 1) A soil test is not required for deck and screen porch additions.
 - 2) A soil test is not required for dwelling additions located in the area designated with lower probability of expansive soils on the attached map (page 3).
 - 3) The soils will be investigated, and the footing will be designed on site by the RDP during footing excavation. A letter documenting that this will be the course of action must be submitted with the building permit application.

FOOTING DESIGN REQUIREMENT

If soils are determined to be expansive, the footing shall be design by the RDP in accordance with the Virginia Construction Code and the footing design shall be submitted with the building permit application.

If the soils are non-expansive, or exceptions 1 or 2 to the soil test requirement are applicable, the footing may be designed using the prescriptive provisions of the Virginia Residential Code.

If exception 3 to the soil test requirement is applicable, a report from the RDP that designed the footing on site must be submitted documenting the soil conditions and the as built footing design. The report must be sealed by the RDP. The report must be submitted prior to requesting the framing inspection.

CODE REFERENCES

Virginia Residential Code Sections R301.1.3 (engineered design), R401.4 (soil test) & R403.1.8 (expansive soils)

Virginia Construction Code Sections 1808.6 (design for expansive soils), 1803.3.1 (scope of soil investigation) & 1803.6 (soil report)

